




EPA GROUND WATER INVESTIGATION

San Mateo Creek Basin Uranium Legacy Site

November 16, 2016
Presentation to BVDA/MASE







PROJECT OBJECTIVE

Characterize ground water quality and impact by legacy uranium mining and milling activities




WHERE IS THE GROUND WATER?


• Alluvial Ground Water


- Shallow ground water
- At depths reaching about 120 feet below ground surface
- In sediments at base of drainage channels (arroyos, creeks)

Bedrock Ground Water

- Deeper ground water
- Hundreds of feet below ground surface
- In rock formations









CONCEPTUAL SITE GROUND WATER MODEL

Generalized Cross Section Through San Mateo Creek Basin




CONCEPTUAL SITE GROUND WATER MODEL





HOW DID MINING OPERATIONS AFFECT GROUND WATER?

- Discharged billions of gallons of mine water to creeks and arroyos
- Water infiltrated into ground
- Increased amount of ground water in alluvial sediments and bedrock
- Changed quality of ground water



Draft – For Discussion Purposes Only Not to Scale

Section 24 Section 35 Mine Mine Section 30 ☆ Cliffside Mine **Section 33** Mine Mine Rio Algom Johnny M Mine Mt Taylor Mine San Mateo 父 Mine **SAND CURVE ROUNDY RANCH** Draft - For Discussion Purposes Only

MINE WATER DISCHARGE

Artificially
Created
Flows in
Creeks
and Arroyos



MULTI-PHASED INVESTIGATION

Phase 1

Shallow Alluvial Aquifer 2012 – 2016 (Completed)

Phase 2

Bedrock & Alluvial Aquifers 2015 – 2017

Phase 3

Develop Conceptual Site Ground Water Model 2017 - 2018



Wet Alluvial Sediments



Bedrock Sandstone



Drill Bit and Piping

PHASE 1 ACTIVITIES COMPLETED

30 Boreholes Drilled

- 6 monitoring wells installed where water encountered
- 24 boreholes dry

15 Existing Wells Sampled

- 10 private wells
- 5 industry monitoring wells
- Includes both alluvial and bedrock wells





Core Sample


PHASE 1 RESULTS SUMMARY

- Attempt to Characterize Alluvial Water Quality had Mixed Results
 - Lack of Natural Saturation in Many Areas Investigated
- Alluvial Water Quality Varies Across Basin
 - Good quality upgradient of mines and mills
 - Poor quality downgradient of mines and mills
- Mine Discharge Water Increased Saturation in Alluvium
- Mine Discharge Water **Draining Out** of Alluvium Today


UPGRADIENT VS DOWNGRADIENT










Alluvial Ground Water









PLANNED ACTIVITIES FOR GROUND WATER INVESTIGATION

